

NOTICE OF COMPLETION  
AND  
AUTHORIZATION TO APPLY THE UL MARK



2013/07/17

Sure Star Computer Co Ltd  
Mr. Dracula Lin  
2-1 Daan Rd  
Shulin  
New Taipei 238, Tw

Our Reference: File E155314, Vol. X1 Project Number 13CA32810  
Your Reference: U311052  
Project Scope: UL/CUL Investigation for Redundant Power Supply, Models: Power Module: M1I-250J1, M1I-300J1, M1I-350J1, M1I-400J1; Redundant Power Supply: R1J-250I1H2A0, R1J-300I1H2A0, R1J-350I1H2A0, R1J-400I1H2A0.  
See Report Reference Number E155314-A11 for details.

Dear Mr. Dracula Lin:

Congratulations! UL's investigation of your product(s) has been completed under the above Reference Number and the product was determined to comply with the applicable requirements. This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Mark at authorized factories under UL's Follow-Up Service Program. To provide your manufacturer(s) with the intended authorization to use the UL Mark, you must send a copy of this notice to each manufacturing location currently authorized under File E155314, Vol. X1.

Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent in the near future. Until then, this letter authorizes application of the UL Mark for 90 days from the date indicated above.

Additional requirements related to your responsibilities as the Applicant can be found in the document "Applicant responsibilities related to Early Authorizations" that can be found at the following web-site:  
<http://www.ul.com/EAResponsibilities>

Any information and documentation provided to you involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL.

We are excited you are now able to apply the UL Mark to your products and appreciate your business. Feel free to contact me or any of our Customer Service representatives if you have any questions.

Very truly yours,

Stanley Tsai  
+886 2 28967790  
Engineer Project Associate  
Stanley.Tsai@ul.com

Reviewed by:

William R. Carney  
847/664-1088  
Chief Engineer Director I  
William.R.Carney@ul.com

CC: SPORTON INTERNATIONAL INC, MR. HANS  
HSIEH

TPIF5D3-5F0E9A