



SURE STAR COMPUTER CO., LTD 添誠資訊股份有限公司

http://www.surestar.com.tw Tel:+886 2 2682 2505

E-mail:info@surestar.com.tw Fax:+886 2 2682 2515

NO.2-1, DAAN ROAD, SHULIN .DIST., NEW TAIPEI CITY 238, TAIWAN

Declaration

FORM VERSION :

A1、20160810

SURE STAR, old name I-STAR, we are wishing to establish better product portfolio, and provide more competitive advantages to customer.

However, new safety regulation IEC 62368 was published, and old safety regulation IEC 60950 will be withdrawn on 2020/12/20.

Presently, we regret to announce that below PSU won't be applied for IEC 62368, include :

TC-1U30、TC-1U35、TC-1U40 for 1U single PSU ;

TC-2U30、TC-2U35、TC-2U40、TC-2U46 for 2U single PSU ;

TC-xxxR2UP、TC-xxxR2UH、TC-xxxR2U, where xxx=300 or 350 or 400 for redundant PSU ;

TC-xxxR、TC-xxxRVN2, where xxx=500 or 550 or 600 or 650 or 700 for redundant PSU ;

TC-950RVN3、TC-1100RVN3、TC-1350RVN3 for redundant PSU ;

TC-1400RVN4、TC-1700RVN4、TC-2000RVN4 for redundant PSU ;

TC-1400RHN4、TC-1700RHN4、TC-2000RHN4 for redundant PSU ;

SS-300R8P、SS-400R8P、R8P-300、R8P-400 for redundant PSU ;

M1C-xxx1 where xxx=400 or 460 or 500 or 550 or 600 and y=A or B or C for redundant module.

Please contact our sales to check if we have enough parts for the order of these products.

ITEM	IEC 60950 only	SUBSTITUTE
#01	TC-1U30、35、40	SS-1U40ES
#02	TC-2U30、35、40、46	SS-2U40、50ES
#03	TC-300、350、400R2UH	R1J
#04	TC-300、350、400R2U	R2A
#05	TC-500、550、600、650、700RVN2	R2A or TCPS1A
#06	TC-950、1100、1350RVN3	Not Available
#07	TC-1400、1700、2000RVN4	Not Available
#08	TC-1400、1700、2000RHN4	Not Available
#09	SS-300、400R8P	R4B or R4S
#10	M1C	Not Available

Company Name : SURE STAR COMPUTER CO., LTD

Issue By : Camel Lin

Issuer Title : CEO

Issue Date : 2019/01/30